

## DRH INSTRUMENT CALIBRATION REQUIREMENTS

1. All calibration must include printed or electronic report of the calibration.
2. Radiation detection instrumentation must be calibrated using a NIST traceable radioactive source.
3. Calibrations must comply with MQSA requirements for NIST measurement assurance agreement -900.2 (XX) and for NIST traceability 900.12(D)(12).
4. The vendor must be A2LA Certified.
5. Instruments shall be delivered to and picked up from the vendor by the agency during the business hours of 8:00 am to 4:30 pm Monday through Thursday.
6. Vendor must be located within a 30-mile radius of the Nashville Radiation Environmental Monitoring central office.
7. Vendor must also provide an after-hours phone number and point of contact for emergency purposes.
8. In the event of an after-hours emergency the vendor must provide the agency physical access to retrieve their calibrated instrumentation.